







▶ AGIE - POWER FEED CONTACT









Image	Item No.	Original No.	Description	Application
	A001	199.484.7	Current supply 9 x 9 x 3 mmT	AC50. DEM250...740 series
	A001G	199.484.7-1	Current supply with tin coating - long life type 9 x 9 x 3 mmT	AC50. DEM250...740 series
	A015	358.684.9	Current supply lower polished	AC100....370HSS series
	A015G	326.824.0	Current supply upper. Tin coated	AC100....370HSS series
	A016	443.474.2	Tungsten Carbide Evolution Exxcellence & Classic 2.3	
	A017	424.914.0	Current supply upper-M6 screw	AC100....370HSS series
	A017G	424.914.0-1	Current supply upper. Tin coated	AC100....370HSS series

## AGIE

	A018	424.934.8	Current supply lower-M4 screw	AC100....370HSS series
	A018G	424.934.8-1	Current supply lower. Tin coated	AC100....370HSS series

### ▶ AGIE - OTHER PARTS

Image	Item No.	Original No.	Description	Application
	A200	326.764.8	Nozzle lower	AC100....370HSS series
	A021	351.594 (174.132)	Dies block upper	AC-50 series AC-250. 315. 400.425. 612. 700. 740 series
	A022	185.763	Schaft complete	AC-50 series AC-250. 315. 400.425. 612. 700. 740 series
	A023	251.563.3	Suction tube for taper cutting. 30*16	

	A027	338.184.5	Suction tube lower	AC100...370HSS series
				
	A031	352.904.7	Casting box	AC-50 series AC-250. 315. 400.425. 612. 700. 740series
	A032	368.624.8	Dies block lower	AC-50 series AC-250. 315. 400.425. 612. 700. 740series
	A033	377.704 (427.444.5)	Horizontal Arm	Replaced by(427.445.5)
	A034	396.414.5	Suction Tube lower	AC100 ... 370HSS
	A035	419.374.4	Suction tube funnel type	AC220
	A036	419.594.7	Suction Tube	AC ... HSS Series